

HDPE Pipe Butt Fusion 101



EMCO
WATERWORKS

SUP **SANDALE**
UTILITY PRODUCTS

A Division of EMCO Corporation

Polyethylene

HDPE: Benefits:

- ✓ corrosion resistant
- ✓ capable of leak free joints
- ✓ is lighter than many other piping materials
- ✓ Has small crack resistance
- ✓ has high flows and is less prone to internal deposit buildup than many other pipes.

Leak Free Joints?

3 ways to get leak free joints in HDPE:

FUSION

There are three main types of HDPE pipe fusion:

- ◆ 1) Butt fusion - todays topic
- ◆ 2) Socket fusion
- ◆ 3) Electrofusion

Each of the above joining methods are similar in that each uses heat and pressure to join HDPE pipe.

7 steps to hdpe butt fusion

1. Secure pipe in machine
2. Face the ends
3. Check alignment
4. Heat
5. Join ends
6. Hold to Fuse / Cool
7. Inspect

- Source: ASTM F2620 / PPI TR-33 North American HDPE Butt fusion standard / procedure



HDPE Pipe Butt Fusion step 1

1. Secure / clamp pipe


- clean pipe to remove stones / dirt
- clamp pipe in machine jaws securely



HDPE Pipe Butt Fusion - Step 2

2. Face the pipe ends

- squares the pipe ends
- removes oxidized layer of pipe



HDPE Pipe Butt Fusion - Step 3

3. Check pipe alignment


- high/low max 10% of pipe wall thickness
- do not fuse a miter into the pipe
- adjust as needed, remove shavings & clean pipe



HDPE Pipe Butt Fusion - Step 4

4. Heat the pipe



- check temperature range 400 F – 450 F
- wipe the heater clean & apply heat to pipe
- until we get the desired melt bead size



HDPE Pipe Butt Fusion - Step 5

5. Join the pipe


- at the calculated fusion pressure
- check melted pipe ends are smooth/glossy
- don't take too long to close



HDPE Pipe Butt Fusion - Step 6

6. Hold pipes


- at the calculated fusion pressure
- for the calculated time
- the fusion happens during this time




HDPE Pipe Butt Fusion - Step 7

7. Inspect visually


- unclamp and inspect
- see visual cues




Visual inspection tips




1. Insufficient heat time; melt bead too small





2. Excessive heat time or pressure applies during heating; melt bead too large



3. Pipe angled into fusion unit



4. Improper "High-Low" alignment





“That's all Folks!”

